




Smoke and Dye-Water Observation Summary

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 54

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\54.tif

Image Status: Image found and displayed.


NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.

DYE TESTING FORM

Sketch (NTS)

Dye Test 54

Show North Arrow



DESIGN CODES		SOURCE TYPE CODES			
1. POSITIVE	1. MAIN SEWER	5. DOWN SPOUT	9. STAIRWELL DRAI	13. STORM DRAIN	
2. NEGATIVE	2. SERVICE LINE	6. DWNSPT CONN.	10. FOUNDATION DRAIN	14. CATCH BASIN	
3. CANNOT TEST	3. TRANSITION JOIN	7. AREA DRAIN	11. BUILDING INTERIOR	15. STORM MH	
	4. CLEAN OUT	8. DRIVEWAY DRAIN	12. MH FRAME/SEAL	16. STORM DITCH	
Additional Comments: TUED IN M.H. 1521162. NO DYE SEEN COMING FROM IN THE PIPE.					



Savin Engineers, P.C.
3 Campus Drive
Pleasantville, NY 10570
Tel: (914) 769-3200, Fax: (914) 747-6686

INSPECTION REPORT


DATE: 04/05/2005	WORK ORDER:	WEATHER: SUNNY, DRY	OPERATOR: J.A.M.	SECTION NR: 29	SECTION NAME:
PRESENT:	VEHICLE: TV 175	CAMERA: PAN/TILT	PRESET:	CLEANED: NO	RATE: 0

STREET: ROCKWOOD AVE. 54 B 1	MAP #1: 1	MH: 1521758
CITY: BALTIMORE	MAP #2:	MH: 1521162
LOCALE: SMALL RESIDENTIAL STREET	TAPE #: JAM 2	TV'D LGTH: 2 ft

INSPECT REASON: DYE TESTING	PIPE SIZE: 8 in
SECTION TYPE: WASTEWATER	MATERIAL: VCP JT LGTH: 3 ft
AREA: 01-WR21	LINING: NO RELINING
	RSRVD:

REMARK: DYE TEST 54 B 1

1:25	DIST	OBSERVATION	RATE	VCR #	PH
------	------	-------------	------	-------	----



inspection begins at downstream manhole, 1521758. LEAKING FROM PIPE SEAL OF LINE FROM M.H. 1521162

00:41:53 44a

INSPECTION IMAGES

CITY:
BALTIMORE

STREET:
ROCKWOOD AVE. 54 B 1

DATE:
04/05/2005

SECTION NR:
29

SECTION NAME:



IMAGE: 44a, TAPE #: JAM 2, 00:41:53
2FT, inspection begins at downstream manhole, 1521758.
LEAKING FROM PIPE SEAL OF LINE FROM M.H. 1521162